References

American Society for Quality Control (1983), *ASQC Glossary and Tables for Statistical Quality Control*, 230 W. Wells Street, Milwaukee, Wisconsin 53203.

American Society for Testing and Materials (1976), *ASTM Manual on Presentation of Data and Control Chart Analysis*, 1916 Race Street, Philadelphia, PA 19103.

Burr, I. W. (1969), "Control Charts for Measurements with Varying Sample Sizes," *Journal of Quality Technology*, 1, 163–167.

Burr, I. W. (1976), *Statistical Quality Control Methods, Volume 16*, New York: Marcel Dekker, Inc.

Crowder, S. V. (1987a), "A Simple Method for Studying Run-length Distributions of Exponentially Weighted Moving Average Charts," *Technometrics*, 29, 401–408.

Crowder, S. V. (1987b), "Average Run Lengths of Exponentially Weighted Moving Average Charts," *Journal of Quality Technology*, 19, 161–164.

Hunter, J. S. (1986), "The Exponentially Weighted Moving Average," *Journal of Quality Technology*, 18, 203–210.

Kume, H. (1985), *Statistical Methods for Quality Improvement*, Tokyo: AOTS Chosakai, Ltd.

Montgomery, D. C. (1996), *Introduction to Statistical Quality Control, Third Edition*, New York: John Wiley & Sons, Inc.

Nelson, L. S. (1983), "The Deceptiveness of Moving Averages," *Journal of Quality Technology*, 15, 99–100.

Nelson, L. S. (1989), "Standardization of Shewhart Control Charts," *Journal of Quality Technology*, 21, 287–289.

Nelson, L. S. (1994), "Shewhart Control Charts With Unequal Subgroup Sizes," *Journal of Quality Technology*, 26, 64–67.

Roberts, S. W. (1959), "Control Chart Tests Based on Geometric Moving Averages," *Technometrics*, 1, 239–250.

Robinson, P. B. and Ho, T. Y. (1978), "Average Run Lengths of Geometric Moving Average Charts by Numerical Methods," *Technometrics*, 20, 85–93.

SAS Institute Inc. (1999), *SAS/GRAPH Software: Reference, Version 8*, Cary, NC: SAS Institute Inc.

SAS Institute Inc. (1999), *SAS/ETS User's Guide: Version 8*, Cary, NC: SAS Institute Inc.

Wadsworth, H. M., Stephens, K. S., and Godfrey, A. B. (1986), *Modern Methods for Quality Control and Improvement*, New York: John Wiley & Sons, Inc.

Wetherill, G. B. (1977), *Sampling Inspection and Quality Control, Second Edition*, New York: Chapman and Hall.

Wortham, A. W. and Heinrich, G. F. (1972), "Control Charts Using Exponential Smoothing Techniques," *Annual Conference Transactions*, American Society for Quality Control, Milwaukee, Wisconsin, 451–458.

Wortham, A. W., and Ringer, L. J. (1971), "Control Via Exponential Smoothing," *The Logistics Review*, 7, 33–40.

The correct bibliographic citation for this manual is as follows: SAS Institute Inc., *SAS/QC® User's Guide, Version 8*, Cary, NC: SAS Institute Inc., 1999. 1994 pp.

SAS/QC® User's Guide, Version 8

Copyright © 1999 SAS Institute Inc., Cary, NC, USA.

ISBN 1–58025–493–4

All rights reserved. Printed in the United States of America. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, by any form or by any means, electronic, mechanical, photocopying, or otherwise, without the prior written permission of the publisher, SAS Institute Inc.

U.S. Government Restricted Rights Notice. Use, duplication, or disclosure of the software by the government is subject to restrictions as set forth in FAR 52.227–19 Commercial Computer Software-Restricted Rights (June 1987).

SAS Institute Inc., SAS Campus Drive, Cary, North Carolina 27513.

1st printing, October 1999

SAS® and all other SAS Institute Inc. product or service names are registered trademarks or trademarks of SAS Institute in the USA and other countries.® indicates USA registration.

IBM®, ACF/VTAM®, AIX®, APPN®, MVS/ESA®, OS/2®, OS/390®, VM/ESA®, and VTAM® are registered trademarks or trademarks of International Business Machines Corporation. ® indicates USA registration.

Other brand and product names are registered trademarks or trademarks of their respective companies.

The Institute is a private company devoted to the support and further development of its software and related services.